



Date: 03/16/07
 File: SS_Residual_Sat_Tc99.grf

INTERA INTERA INCORPORATED
 9111A Research Blvd.
 Austin, Texas 78758

CJ **COOK-JOYCE INC.**
 ENGINEERING AND CONSULTING
 812 WEST ELEVENTH
 AUSTIN, TEXAS 78701-2000
 (512) 474-8087 FAX (512) 474-8483

Sensitivity at the
 Outflow Boundary
 to the Residual
 Saturation of the
 Fracture

Figure 6-8t